


ALLOTMENT Digging Planter Assembly Instructions







PARTS required






TOOLS required








Digging Planter to be pre-assembled UP TO STEP Installation on site jump to this step



2


Assembly the first RING

Using 4 x T1 timbers




3

Assemble the second ring Using the remaining T1 timbers & T1A timbers



4


The 2 ring are to be positioned as shown below





Screw T2 timbers (floor support) to the lower T1 ring


Using 80mm brass screws (5 per T2 timber)



6

Attach the remaining T2 timbers


Using 80mm brass screws






Screw T3 timbers to the T2 timbers & T1 lower ring

Using 40mm / 120mm brass screws & angle cleats (use 40mm brass screws to attach angle cleats to T3 timbers








Screw H1 (floor section) to the T2 timbers

Using 11 x 40mm brass screws


...Repeat for the second floor section



9


Attach the Assembly with floor & upper ring to the T4 timbers

Using 120mm brass screws







Screw the T1 'rings to the T4 timbers as shown



11

Main assembly complete





13

Repeat for the second divider

